

All COR ISO Recommendations

Latent Condition, Seismic and ISS

Friday, October 12, 2012 12:47:50 PM

Type	Rec #	ABU	Unit	Year (I/R)	LC or ISS Question #	LC Question ISS Question Seismic Area	Observation	Recommendation	Resolution	Due Date	Assigned To	Status
Latent Condition	216	Isomax	#20 PLANT	2003			PSA vessels in #20 Plant have experienced multiple failures and repeat failures. When PSA vessels fail, hydrogen leaks to the atmosphere.		Quarterly monitoring program in place by inspections. A project is in place to look at the replacement options for 20 Plant. An engineering review has been performed on the vessels by Peter Risse and Dave Bosi which predicts useful into 2006.	1/1/2007	Sadekoski, Duane E.	Completed
Seismic	632	Isomax	#20 PLANT	2010		none	The engineer has no recommendations for repairs.				Crow, Mark A.	Completed